



1/13

**FIG. 1**



2/13


**FIG. 2**



This diagram illustrates a mechanical linkage system. A long arm 18 is pivoted at point P to a horizontal link 11. This link 11 is connected to a complex arrangement of gears or pulleys 16 and 32, which are mounted on a frame 34. Other components include a lever 33, a connecting rod 35 with pin 35a, a guide surface 36, and various structural elements like 20, 20a, and 31. A cross-section C is shown at the top right.


4/13

**FIG. 4**




5/13

**FIG. 5**




6/13

**FIG. 6**




7/13

**FIG. 7**




8/13

***FIG. 8A***




***FIG. 8B***






9/13

**FIG. 9**




10/13

***FIG. 10A***




***FIG. 10B***




11/13

**FIG. 11**




12/13

***FIG. 12A***



***FIG. 12B***



13/13

**FIG. 13**

